


Specification



Accessories for CWS500

- IEC 61000-4-6

For tests as per IEC 61000-4-6 different accessories are required



Accessories as per IEC 61000-4-6

Clamps:

EM Clamp	EM Clamp type EM 101
MDS 21	Emission measurement clamp
F-120-9A	Current injection clamp BCI from FCC
FCC-BCICF-4	Calibration Fixture for BCI clamp (jig) from FCC



Adapters for CDN calibration:

CWS-CAL	Basic calibration kit including R100 , cables and carrying case
CA EM	Cal Kit for EM 101



General accessories:

T 50	Matching resistor 50Ω for non used CDN's
ATT 6/75	6dB/75W attenuator
R 100	100Ω to 150Ω matching adapter